



Chernoff Hall: Room 117

Additional Photos:



Image Description: Entryway door to Chernoff Hall room 117 classroom. Doorway is a wooden double door, with two handles in the middle.



Image Description: Image of the podium at the front of the classroom, on the right-hand side. A phone is located on the left side of the podium. This podium is not moveable or height adjustable. This podium is not accessible.



Image Description: View of the classroom from the instructor's podium. The classroom has seven rows of chairs, with tiered steps to access tables in the middle and back area of the classroom. The entryway door is located at the back of the classroom on the left-hand side. This classroom is not accessible for instructors.



Image Description: View of the classroom from a student seat at the rear of the room. Instructor's podium is located at the front of the room on the left-hand side (from a student's point of view). Sliding blackboards are located on the front wall. A digital projector on the ceiling projects onto a screen, which extends from the ceiling. The entryway door is located on the right side of the image. This classroom is accessible for students.



Image Description: The podium is equipped with a document camera, lecture capture, a set of microphones and connection cords to project media.

For more information about accessibility on campus, please refer to the [Accessibility Hub](#) or the [Facilities Building Directory](#).